

To: Vann, Bradley[Vann.Bradley@epa.gov]; Juett, Lynn[Juett.Lynn@epa.gov]; 'Seabaugh, Ryan'[ryan.seabaugh@dnr.mo.gov]
Cc: McGahren, John[jmcgahren@morganlewis.com]; Feingold, Stephanie R.[sfeingold@morganlewis.com]; 'Guariglia, Dale'[daguariglia@BryanCave.com]; Russell R. Eggert[REggert@LATHROPGAGE.COM]; Johnson, Nicholas R. (LG)[NJohnson@LATHROPGAGE.COM]; 'Beck, Bill (LG)'[WBeck@LATHROPGAGE.COM]; Merrigan, Jessie[JMerrigan@LathropGage.com]; 'Warren, Victoria'[VWarren@republicservices.com]; Fanning, Erin[EFanning@republicservices.com]; Dan Feezor[dfeezor@feezorengineering.com]; 'Mike Bollenbacher'[mikeb@auxier.com]; 'Cecilia Greene'[cgreene@auxier.com]; Bob Jelinek[bobjelinek@emsidenver.com]
From: Paul Rosasco
Sent: Fri 2/19/2016 7:33:44 PM
Subject: RE: Responses to Comments on the Comprehensive Phase 1 Report
[Responses to EPA Comments West Lake OU-1 Phase 1 Comp Rpt 2-19-16.pdf](#)

Brad,

Attached please find revised Responses to EPA comments on the Comprehensive Phase 1 report. Specifically, we have revised the response to Comment No. 27, to remove the last sentence of our earlier response, which stated *"The text has also been revised to indicate that based on the 1971 estimated topographic surface, a topographic low appears to be present in 1971 in the area where these borings were subsequently drilled."* After looking at the 1971 topographic surface again and the associated aerial photo (to be provided as Figures 12a and 12b with the updated report), we observed that the area near borings 1D-7, 1D-9 and 1D-15 was not a topographic low in 1971, but instead was a flat surface that was elevated above the surrounding area within Area 1.

No other changes have been made.

Please accept our apologies for any confusion, and for not capturing this change in the Responses to EPA comments that we submitted earlier today. Let us know if you have any questions

From: Paul Rosasco [mailto:paulrosasco@emsidenver.com]
Sent: Friday, February 19, 2016 7:01 AM
To: 'Vann, Bradley' <Vann.Bradley@epa.gov>; 'Juett, Lynn' <Juett.Lynn@Epa.gov>; 'Seabaugh, Ryan' <ryan.seabaugh@dnr.mo.gov>
Cc: McGahren, John <jmcgahren@morganlewis.com>; Feingold, Stephanie R. <sfeingold@morganlewis.com>; 'Guariglia, Dale' <daguariglia@BryanCave.com>; Russell R. Eggert (REggert@LATHROPGAGE.COM) <REggert@LATHROPGAGE.COM>; Johnson,

Nicholas R. (LG) <NJohnson@LATHROPGAGE.COM>; 'Beck, Bill (LG)' <WBeck@LATHROPGAGE.COM>; Merrigan, Jessie <JMerrigan@LathropGage.com>; 'Warren, Victoria' <VWarren@republicservices.com>; Fanning, Erin <EFanning@republicservices.com>; Dan Feezor <dfeezor@feezorengineering.com>; 'Mike Bollenbacher (mikeb@auxier.com)' <mikeb@auxier.com>; 'Cecilia Greene' <cgreene@auxier.com>; Bob Jelinek <bobjelinek@emsidenver.com>
Subject: Responses to Comments on the Comprehensive Phase 1 Report

Brad,

Attached are responses to EPA's January 28, 2016 comments on the December 16, 2015 Comprehensive Phase 1 Report for West Lake Landfill OU-1. We will be submitting the revised report later today.

Paul V. Rosasco P.E.

Engineering Management Support, Inc.

7220 West Jefferson Avenue, Suite 406

Lakewood, CO 80235

Office (303) 940-3426 ext. 5

Mobile (303) 808-7227

paulrosasco@emsidenver.com

This email has been sent from a virus-free computer protected by Avast.
www.avast.com